

The logo for BOA SKI features the words "BOA" and "SKI" stacked vertically in a bold, sans-serif font. A large, stylized, cursive letter "S" is positioned to the right of the text, with its top loop extending over the word "BOA" and its bottom loop extending under the word "SKI".

BOA SKI ONTARIO LTD.

Head Office: P.O. Box 447, NORTH BAY, ONTARIO - TELEPHONE (705) 472-5800
Branch: 1362 Blundell Rd., MISSISSAUGA, ONTARIO - TELEPHONE (416) 277-1491

November 17, 1972.

TO ALL BOA SKI DEALERS:

Further to our discussions at the recent service schools please find enclosed:

1. Boa Ski parts price list
2. Dealer warranty pack
3. Hirth spec sheets
4. List of Hirth dealers
5. Hirth parts price list

We list below a brief summary of some of the points brought out at the meetings.

Warranty:

You will find in your warranty packs a statement of the Boa Ski warranty policy. Except in the most unusual cases this policy will be strictly adhered to. You will note that according to the warranty procedures it is not necessary to send the defective parts in with your claim. This is not correct. Please send all parts to us for inspection along with your claim. Warranty will not be allowed unless we have the defective parts. Send all claims and parts to Boa Ski Ontario Limited, not to the factory. You must use the enclosed warranty claim form, do not submit claims on any other type of claim form. The claim form must be completely filled in (except price) showing all details. Warranty labour is paid at the rate of \$6.50 per hour according to the 1971-72 flat rate.

JLO and Hirth warranty can be submitted to us or through the engine manufacturers service organization, wherever you purchase your parts. If you purchase your parts from us and submit your warranty to us, be sure to show engine make and model on the claim.

Parts:

We have a complete stock of parts for machines up to this model year. The 1973 parts should be in this week. Stock up now and avoid back orders during the busy season. Order owner's books, wiring diagram and warranty cards for all machines received without this information. Order choke kits for MK 11 machines received without external chokes installed. Order metal gas tank fitting and engine cover grommet for all 1972 MK 11s. Be sure when installing gas tank fitting to rearrange the pick up and return lines so that they are well separated in the tank.

QUALITY AND DEPENDABILITY FIRST

Page 2.

We have been advised by the factory and the clutch manufacturer that there is a possible mix up in the springs and weights on the two models of clutches in use this season. Please note the following:

Machines using 292cc & 340cc twin engines: Spider weights stamped with #6
Length of 4508 coil spring 4"
Engagement RPM - 38-4000

Machines using 399cc & 440cc twin engines: Spider weights stamped with #0
Length of 4508 coil spring 4½"
Engagement RPM - 34-3600

Should you have a machine that won't engage until 5000 or more RPM, check the spring length and if too long cut spring to proper length as per above. In some cases the clutch bolt may be difficult to remove as it will not clear the side of the machine. In this case, loosen centre bolt and pull out as far as possible, then loosen 0213 captive bolt. This will allow sufficient play to remove centre bolt. Be careful when removing 0213 captive bolt as the cover is spring loaded, use a clamp or some means of holding the clutch together until captive bolt is off, then release 0006 cover slowly.

Please find attached a list of service tools and manuals available for this year.

Our service schools were a complete success with over 100 dealers attending. We had some very good discussions and exchanging of ideas. To all those who attended - thanks for making the schools a success. To those who couldn't be with us - you missed a great meeting.

Yours truly,

BOA SKI ONTARIO LIMITED,

J. Chadbourne.

Jack Chadbourne,
Parts Manager.

JC/do
Encl.

Boa Ski Service Manual: Contains parts books and price lists on Boa Ski, Hirth, Walbro, Tillotson & JLO. Service information on Hirth, Walbro & Tillotson. Includes large Walbro wall chart.
 Dealer Net \$6.50

Hirth Parts Manual: Contains parts breakdown on all Hirth engines since 1967. (This manual is included in the Boa Ski manual above)
 Dealer Net \$5.00

JLO Service Manual: Contains disassembly and assembly instructions and specs on single and twin cylinder JLO engines.
 Dealer Net \$5.00

Snowmobile Trade in Guide: Shows original value and trade in value of all makes of snowmobiles
 Dealer Net \$4.00

W120	Flywheel Puller - Hirth Engines	Net	15.00
W123	Flywheel Puller - Hirth axle fan engines	Net	16.00
444.31.814/10	JLO Flywheel Puller L295	Net	6.60
444.31.843/10	JLO Flywheel Puller axle fan engines	Net	8.05
444.31.873/100	JLO Flywheel Puller L230	Net	3.75
263	Central Dial Guage	Net	35.00
200W	Roller Kit for above Guage	Net	3.50
276	Angle adaptor for 263 Guage	Net	17.50